### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

 PATENT NO.:
 6,862,646
 GRANT DATE:
 March 1, 2005

 INVENTOR(S):
 Thomas J. Bonola, et al.
 ATTY. DOCKET NO.:
 200304307-1

SERIAL NO.: 10/034,464 CONFIRMATION NO.: 9354

FILED: December 28, 2001

TITLE: METHOD AND APPARATUS FOR ELIMINATING

THE SOFTWARE GENERATED READY-SIGNAL TO HARDWARE DEVICES THAT ARE NOT PART

OF THE MEMORY COHERENCY DOMAIN

# REQUEST FOR ISSUANCE OF CERTIFICATE OF CORRECTION

#### COMMISSIONER FOR PATENTS ALEXANDRIA, VA 22313-1450

Sir:

The assignee of the entire interest in the above-identified patent respectfully requests that a Certificate of Correction be issued in accordance with 37 CFR 1 322

Enclosed herewith is a complete copy of Form PTO 1050 (Rev. 3-82) describing the various errors involved in the above patent. The errors that occurred under Rule 322, appear in Column and Line format.

Issuance of a Certificate of Correction to correct these errors is therefore respectfully requested.

We shall appreciate your returning to us one executed copy of this Certificate of Correction for attachment to our Letters patent.

Respectfully submitted

William P. O'Meara, Esq. Reg. No. 29,962

Hewlett-Packard Company

Legal Department P.O. Box 272400 MS 35 Ft. Collins, CO 80528-9599 Ph. No. (970) 898-3886 PTO/SEA44 (04-05)
Approved for use through 04/30206 (065-0403)
U.S. Patient and Transmit Office. U.S. DEPATRICENT OF COMMENT
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it delaptive a validation of the property of the control of the c

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page _	1_0	of1_	
--------	-----	------	--

APPLICATION NO.: 10/034,464
ISSUE DATE : March 1, 2005

PATENT NO.

INVENTOR(S) : Thomas J. Bonola, et al.

6.862.646

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### IN THE CLAIMS

Claim 35, Column 10, line 62, after "allowing the" insert --hardware device--

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Hewlett-Packard Co.

P.O. Box 272400 MS35

Ft. Colllins, Colorado 80528-9599

This collection of information is required by 37 CPR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO) to process) an application, Confidentially is governed by 35 U.S.C. 122 and 37 CPR 1.14. This collection is selfect to take 0.19 hour to complete, including gathering, preparing, and submitting the completed application from to the USPTO. Time will very depending upon the individual case. Any comments on the amount of time you require to incomplete this form and/or suggestestor for reducing this batches, should be sent to the Certification of Cer